

**COMPLETED PLAYGROUND
EQUIPMENT WORK
SOLDOTNA MAINTENANCE SHOP
Summer 2004**

School

North Star Elementary

Work Completed

Laid out new playground area
Installed new Big Toy
Built new 150' long retaining wall to contain pea gravel
Installed pea gravel
Installed Fire Truck Toy, new Funnel Ball Toy, benches
Reset swings to approved height

Cooper Landing School

Removed and reset Big Toy (due to ground heaving)
Reset swings to approved height
Straightened basketball backboard posts, installed new backboards

Moose Pass School

Removed old playground fill, installed new pea gravel

Sterling Elementary

Installed new Tire Tunnel

**COMPLETED PLAYGROUND
EQUIPMENT WORK
SOLDOTNA MAINTENANCE SHOP
Summer 2005**

School

Soldotna El.

Removed, rebuilt, and replaced the "Post Fort"
Removed the teeter-totters

Sears El.

Removed the teeter-totters

Tustumena El.

Removed and reset some of the posts on the Wood Toy

Moose Pass

Installed new pea gravel surface

Mountain View El.

Reset swingsets, due to exposed concrete at base
Straightened basketball backboard posts

Redoubt El.

Replaced beams on the Wood Toy
Replaced the overhead sliders
Replaced the cables on the overhead walkway

**COMPLETED PLAYGROUND
EQUIPMENT WORK
SOLDOTNA MAINTENANCE SHOP
Summer 2006**

School

Seward El.

Removed Fence
Removed 500 cubic yards of crushed rock (did not meet safety standards for use)
Removed all existing playground equipment
Installed Big Toy, Cosmic Warp, Stand-up See-saw, Orbiter, Loopy Warp, Drum
Installed toys purchased by school
Relocated swings to the proper height and zone usage
Installed Typar underlayment
Installed 500 cubic yards of pea gravel
Installed retainign perimeter for pea gravel
Installed drainage around playground
Reinstalled fence

Redoubt El.

Removed existing Wood Big Toy
Excavated & removed existing fill
Installed new Typar underlayment
Installed 160 cubic yards of new pea gravel
Relocate Spring Toys
Installed new benches

Soldotna El.

Installed new Teeter-totters
Installed new school-purchased climbing wall
Removed beams

Sears El.

Installed new Teeter-totters

Sterling El.

Installed new Teeter-totters

Tebughna School

Installed new Swingset, Stand-Up Cyclor and Stand-Up See-saw

Tutstumena El.

Removed old tire swing set

**PROPOSED PLAYGROUND
EQUIPMENT WORK
SOLDOTNA MAINTENANCE SHOP
Summer 2007 - Summer 2009**

School

Sterling El. (2007)

Removal of the wood play toy
Removal of the existing fill
Grade the playground for drainage
Install new big toy
Install Typar underlayment and new pea gravel
Install retaining wall to contain pea gravel

Investigate possible relocation of the existing play ground equipment

Hope School (2007)

Removal of the wood Big Toy

K. Beach El. (2008)

Removal of the wood toy
Removal of the existing fill
Grade the area for drainage
Install new big toy
Install Typar underlayment and pea gravel
Install retaining wall to contain pea gravel

Tustumena El. (2008)

Removal of the wood toy
Removal of the existing fill
Grade the area for drainage
Install new big toy
Install Typar underlayment and pea gravel
Install retaining wall to contain pea gravel

**PLANNED PLAYGROUND EQUIPMENT WORK
HOMER MAINTENANCE SHOP
Summer 2007**

SCHOOL

MCNEIL

**TWO - TIRE SWINGS
ONE - RB-310 CLIMBING WALL**

NIKOLAEVSK

**TWO - TIRE SWINGS
ONE - RB-520 CLIMBING WALL**

PAUL BANKS

THREE - TIRE SWINGS

SELDOVIA

ONE - RB-320 CLIMBING WALL

NANWALEK

MAINTENANCE / REPAIR WORK

**THREE-YEAR PLAN FOR PLAYGROUND EQUIPMENT
HOMER MAINTENANCE SHOP
2008-2010**

SCHOOL	EQUIPMENT TO BE REMOVED	EQUIPMENT TO BE INSTALLED
MCNEIL AND NIKOLAEVSK INSTILLATION DATE SUMMER '08		
MCNEIL	2 - HORIZONTAL LADDERS 1 - SLIDE CLIMBER	EXCERCENTER PE-505
NIKOLAEVSK	2 - HORIZONTAL LADDERS	EXCERCENTER PE-505 TRIPLE SHOOTOUT
PAUL BANKS AND NIKOLAEVSK INSTILLATION DATE SUMMER '09		
PAUL BANKS	1 - HORIZONTAL LADDER	T - SWING CLIMBING TUNNEL
CHAPMAN		EXCERCENTER PE-505 TIRE SWING
NINILCHIK AND P. GRAHAM INSTILLATION DATE SUMMER '10		
NINILCHIK		TIRE SWING
P. GRAHAM		TRIPLE SHOOTOUT

ITEMS TO BE REMOVED DO NOT MEET THE REQUIREMENTS OF
THE NATIONAL PLAYGROUND SAFETY INSTITUTE